MALAYSIA

TEL : 6-03-8529 1318
FAX : 6-03-8529 1310
Email : ais@caam.gov.my
Web : aip.caam.gov.my

CIVIL AVIATION AUTHORITY OF MALAYSIA AERONAUTICAL INFORMATION SERVICES LEVEL 2, WEST WING TERMINAL NORTH JALAN CTA 3

KUALA LUMPUR INTERNATIONAL AIRPORT 64000 KLIA, SEPANG SELANGOR DARUL EHSAN AIP

Supplement 24/2023

22 JUN 2023

MULU AIRPORT (WBMU) RUNWAY SURFACE CRACK AND DEPRESSION

1 PURPOSE

- 1.1 The purpose of these AIP Supplement is to notify presence of surface cracking and depression at Mulu Airport. Surface cracking observe on right and left side of taxiway A near holding point while the depression was observed approximately 200 meters on the right-hand side of the old turning pad towards Runway 21.
- 1.2 The related information is as follows:

DISPLACED THRESHOLD RWY 03 PAPI 3* HIGH INTENSITY SMPLE APP, LIGHTS SCALE: METRES CONTROL TOWER DISPLACED THRESHOLD RWY 21 SCALE: METRES

MULU AIRPORT

- 1.3 This AIP SUP supersedes NOTAM D0317/23 and D0318/23.
- 1.4 Any updates or cancellation of this AIP Supplement will be notified by NOTAM.