



Jabatan Penerbangan Awam Malaysia  
Aras 3, Blok Podium  
No 27, Persiaran Perdana, Presint 4  
Pusat Pentadbiran Kerajaan Persekutuan  
62618, Putrajaya  
Malaysia

---

## Department of Civil Aviation, Malaysia

### Director General Notice

---


#### **LIMITATION WITH REGARDS TO PERMIT TO FLY IN THE CASE OF A PILOT OF AN AIRCRAFT USED IN GENERAL AVIATION OPERATION**

##### **1. Introduction**

- 1.1 In exercise of the powers conferred by Regulations 29 and 202 of the Civil Aviation Regulations 2016, the Director General makes this Director General Notice (“Notice”).
- 1.2 This Notice is published by the Director General under section 240 of the Civil Aviation Act 1969 [Act 3].
- 1.3 Following the aircraft accident at Seletar Airport, Singapore in October 2015, the Transport Safety Investigation Bureau, Singapore has made several safety recommendations. The purpose of this Notice is mandating those safety recommendations.
- 1.4 This Notice shall come into force on 1<sup>st</sup> August 2017.

**2. Limitation with regards to Permit to Fly**

- 2.1 This Notice is to remind a pilot of an aircraft used in any general aviation operation who holds a valid permit to fly issued by the Director General shall not fly the aircraft outside Malaysia or over any State.
- 2.2 Paragraph 2.1 shall apply to the pilot as specified in paragraph 2.1 even the pilot holds a valid flight plan which allow him to fly outside Malaysia or over any State.



**DATO' SRI AZHARUDDIN ABDUL RAHMAN**  
**Director General of Civil Aviation**  
**Malaysia**