

TEL : 6-03-8529 1318  
FAX : 6-03-8529 1310  
Email : ais@caam.gov.my  
Web : aip.caam.gov.my

**MALAYSIA**  
CIVIL AVIATION AUTHORITY OF MALAYSIA  
AERONAUTICAL INFORMATION SERVICES  
LEVEL 2, WEST WING TERMINAL NORTH  
JALAN CTA 3  
KUALA LUMPUR INTERNATIONAL AIRPORT  
64000 KLIA, SEPANG  
SELANGOR DARUL EHSAN

**AIP SUPP  
37/2023**

Effective from 11 OCT 2023  
to 18 MAY 2024  
Published on 11 OCT 2023

**MALACCA AIRPORT (WMKM)  
SUSPENSION OF INSTRUMENT APPROACH PROCEDURE  
(IAP) RWY03**

The purpose of this AIP Supplement is to notify suspension of Malacca Airport IAP RWY 03.

1. This AIP Supplement issued as replacement of NOTAM A2310/23
2. The suspension is temporary due to obstacle as shown below:

<b>Obstacle ID</b>	<b>Type of Obstacle</b>	<b>Obstacle Position</b>	<b>Height (M) AMSL</b>	<b>Type and Colour of Lighting</b>	<b>Remarks</b>
<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>
Encore Melaka	Building	021140.46N 1021323.28E	155 (508.52FT)	Lighted	Permanent Aerodrome Obstacle
Atlantis Apartment	Building	021145.25N 1021352.55E	155 (508.52FT)	Lighted	Permanent Aerodrome Obstacle
The Sail	Mobile Crane	021128.00N 1021359.00E	255 (836.60FT)	Crane with chequere flag and lighted	Crane is expected to remain in position until Dec 2026

3. Pilots are advised to exercise caution during landing on RWY03 or taking-off from RWY21
4. The detail of IAP temporary suspended are as below:
  - a) AD 2-WMKM-8-1 (ILS Z OR LOC Z RWY03)
  - b) AD 2-WMKM-8-3 (ILS Y OR LOC Y RWY03)
  - c) AD 2-WMKM-8-5 (VOR Z 13 DME ARC RWY03)
  - d) AD 2-WMKM-8-7 (VOR Y RWY03)
  - e) AD 2-WMKM-8-9 (RNP Y RWY03)
5. This suspension remains until **18 May 2024** or until new IAP has been published.

- END -