TEL	: 6-03-8529 1318	
TEL FAX	: 6-03-8529 1310	
Email Web	: ais@caam.gov.my	
Web	: aip.caam.gov.my	

MALAYSIA CIVIL AVIATION AUTHORITY OF MALAYSIA AERONAUTICAL INFORMATION SERVICES LEVEL 2, WEST WING TERMINAL NORTH JALAN CTA 3 KUALA LUMPUR INTERNATIONAL AIRPORT 64000 KLIA, SEPANG SELANGOR DARUL EHSAN

AIRAC AIP 16/2024

Effective from 21 MAR 2024 to 30 JUN 2024 Published on 08 FEB 2024

## KUCHING INTERNATIONAL AIRPORT (WBGG) RUNWAY GUARD LIGHT UNSERVICEABLE

1. The following changes are in effect until 30 June 2024:

## WBGG AD 2.9 SURFACE MOVEMENT GUIDANCE AND CONTROL SYSTEM AND MARKINGS

3	Stop bars and runway guard lights	Runway guard lights for TWY A, A1, A2, B and C are
	(if any)	unserviceable due to maintenance works.

## WBGG AD 2.20 LOCAL AERODROME REGULATIONS (ADDITIONAL)

2.20.7 Pilots are advised to exercise caution when taxiing on the taxiways.

\*\*\*\*

2. This AIRAC AIP Supplement will remain in force until 30 June 2024. Any changes to this AIRAC AIP supplement will be notified through NOTAM.

- END -