
TEL : 6-03-8529 1318
FAX : 6-03-8529 1310
Email : ais@caam.gov.my
Web : aip.caam.gov.my

MALAYSIA
CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
LEVEL 2, WEST WING TERMINAL NORTH
JALAN CTA 3
KUALA LUMPUR INTERNATIONAL AIRPORT
64000 KLIA, SEPANG
SELANGOR DARUL EHSAN

**AIRAC AIP
22/2024**

Effective from 18 APRIL 2024
to UFN
Published on 07 MAR 2024

**KOTA KINABALU INTERNATIONAL AIRPORT (WBKK)
PRECISION APPROACH LIGHT RUNWAY 02, AIRCRAFT STAND TAXI LANE, AND
APRON TAXIWAY AT TERMINAL 1**

1 Introduction

1.1 This AIRAC AIP Supplement is to inform all concerned about the:

- a) Unserviceable of Precision Approach Light Runway 02; and
- b) Aircraft stand taxi lane and apron taxiway at Terminal 1 temporarily not permitted for aircraft type B747

2 Contacts

Name/designated: JEFRY BIN RAMLI (Airport Manager Kota Kinabalu International Airport)
TEL: 088 – 325 544
e-mail: jefry@malaysiaairports.com.my

3 Validity

3.1 This AIRAC AIP Supplement will remain current until further notice. Any changes to this AIP Supplement will be notified through NOTAM.

- END -