MALAYSIA

TEL : 6-03-8529 1318 FAX : 6-03-8529 1310 Email : ais@caam.gov.my Web : aip.caam.gov.my CIVIL AVIATION AUTHORITY OF MALAYSIA AERONAUTICAL INFORMATION SERVICES LEVEL 2, WEST WING TERMINAL NORTH JALAN CTA 3

KUALA LUMPUR INTERNATIONAL AIRPORT 64000 KLIA, SEPANG SELANGOR DARUL EHSAN AIRAC AIP 37/2024

Effective from 11 JUL 2024 to UFN Published on 30 MAY 2024

ALOR SETAR / SULTAN ABDUL HALIM AERODROME (WMKA) UNSERVICEABLE OF TAXIWAY EDGE LIGHT

1 INTRODUCTION

- 1.1 The following information in effect until further notice:
- 1.2 TWY edge light U/S on TWY A from TWY C to TWY A04 from 11th July 2024 until further notice.
- 1.3 Pilot to exercise caution during taxi.
- 1.4 Visiting aircraft to use TWY A22 and TWY B when taxiing to air movement.

2 VALIDITY

2.1 This AIRAC AIP Supplement will remain in force until further notice. Any updates, changes and cancellation of this AIRAC AIP Supplement will be notified through NOTAM.

- END -