

PHONE: 6-03-8778 4106
Email: ais@caam.gov.my
URL: aip.caam.gov.my

MALAYSIA
CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
AIR TRAFFIC CONTROL TOWER (TOWER WEST)
JALAN KLIA 2/4,
64000 KLIA,
SELANGOR DARUL EHSAN
MALAYSIA.

AIRAC AIP SUP
08/25
Effective Date: 20 MAR 2025
to UFN
Publication Date: 06 FEB 2025

**KOTA KINABALU INTERNATIONAL AIRPORT (WBKK)
SUSPENSION OF INSTRUMENT FLIGHT PROCEDURES
FOR RUNWAY 02 AND 20**

1 INTRODUCTION

- 1.1 The purpose of this AIP Supplement is to notify the aviation industry of the suspension of instrument flight procedures for Kota Kinabalu International Airport due to obstacles.

2 SUSPENDED INSTRUMENT FLIGHT PROCEDURES

NO	SUSPEND	AVAILABLE	AIP REFERENCE PAGE
1	LOC Z RWY 02	ILS Z RWY 02	PAGE AD 2-WBKK-8-3
2	VOR Z RWY 02	-	PAGE AD 2-WBKK-8-5
3	LOC Z RWY 20	ILS Z RWY 20	PAGE AD 2-WBKK-8-9
4	LOC Y RWY 20	ILS Y RWY 20	PAGE AD 2-WBKK-8-11
5	VOR Z RWY 20	-	PAGE AD 2-WBKK-8-13
6	VOR Y RWY 20	-	PAGE AD 2-WBKK-8-15

3 OBSTACLES AFFECTED THE INSTRUMENT FLIGHT PROCEDURES

- 3.1 Obstacles data:

No.	Type	Name	Height FT AMSL	Coordinate	OLS Area
1	Building	The Pinnacle Condo	422.24	055924.26 N 1160459.93 E	Conical
2	Building	Jesselton Quay A	386.81	055928.60 N 1160453.33 E	Approach/Take Off
3	Building	Jesselton Quay B	386.81	055926.86 N 1160451.58 E	Approach/Take Off
4	Building	Peak Vista	478.99	055944.47 N 1160509.90 E	Approach/Take Off
5	Building	Harington Suites	426.50	055742.09 N 1160444.79 E	Inner Horizontal
6	Building	Lido Avenue A	331.69	055622.99 N 1160449.33 E	Inner Horizontal
7	Building	Lido Avenue B	333.66	055621.94 N 1160451.25 E	Inner Horizontal

No.	Type	Name	Height FT AMSL	Coordinate	OLS Area
8	Building	Avani Hotel	507.38	055648.99 N 1160527.34 E	Inner Horizontal
9	Building	Astoria Tower	507.38	055650.94 N 1160528.16 E	Inner Horizontal
10	Building	Shorea Tower	507.38	055649.55 N 1160530.36 E	Inner Horizontal
11	Building	Parkhill Residence	507.38	055647.77 N 1160529.72 E	Inner Horizontal
12	Building	Garden Bundusan A	372.54	055623.85 N 1160550.95 E	Inner Horizontal
13	Building	Garden Bundusan B	372.54	055622.68 N 1160552.46 E	Inner Horizontal

See Attachment A

4 VALIDITY

- 4.1 This AIRAC AIP Supplement supersedes NOTAM **D0019/25** and will remain in force until further notice. Any updates, changes, and cancellations to this AIRAC AIP Supplement will be notified through NOTAM.

- END -

