#### **MALAYSIA**

PHONE: 6-03-8778 4106 Email ais@caam.gov.my URL: aip.caam.gov.my CIVIL AVIATION AUTHORITY OF MALAYSIA AERONAUTICAL INFORMATION SERVICES AIR TRAFFIC CONTROL TOWER (TOWER WEST) JALAN KLIA 2/4,

64000 KLIA, SELANGOR DARUL EHSAN MALAYSIA. AIRAC AIP SUP 42/25

Effective Date: 04 SEP 2025 to 04 SEP 2027

Publication Date: 24 JUL 2025

# LABUAN AIRPORT (WBKL) INCONSISTENT INTERVAL DISTANCE OF APPROACH LIGHTING FOR RUNWAY 14

## 1 INTRODUCTION

1.1 This AIRAC AIP Supplement is to inform all concerned as follows:

#### **WBKL AD 2.14 APPROACH AND RUNWAY LIGHTING**

RWY Designator	Remarks
14	Inconsistent interval distance of approach lighting for Runway 14. Pilot to exercise caution during landing.

\*\*\*\*

#### 2 CONTACTS

2.1 Any information and queries to contact:

Name : Mr. Awang Henapi Kadir

Designated : Head of Operations, MASB Labuan Airport

Email : henapi@malaysiaairports.com.my

### 3 VALIDITY

3.1 This AIRAC AIP Supplement will remain in force until the information is published in AIP Malaysia. Any updates, changes and cancellation to this AIRAC AIP Supplement will be notified through NOTAM.

- END -