

TEL : 6-03-8529 1318
FAX : 6-03-8529 1310
Email : ais@caam.gov.my
Web : aip.caam.gov.my

MALAYSIA
CIVIL AVIATION AUTHORITY OF MALAYSIA
AERONAUTICAL INFORMATION SERVICES
LEVEL 2, WEST WING TERMINAL NORTH
JALAN CTA 3
KUALA LUMPUR INTERNATIONAL AIRPORT
64000 KLIA, SEPANG
SELANGOR DARUL EHSAN

**AIRAC AIP
32/2024**

Effective from 13 JUN 2024
to 31 AUG 2024
Published on 02 MAY 2024

**LABUAN AIRPORT (WBKL)
UNEVEN RUNWAY SURFACE**

1 INTRODUCTION

1.1 The following information concerning Labuan Airport (WBKL) will take place due to uneven runway surface from 13th June 2024 until 31st August 2024.

WBKL AD 2.12 RUNWAY PHYSICAL CHARACTERISTICS

4	Remarks	UNEVEN RWY SFC 1) RWY 14 - FM THR TIL 914 M 2) RWY 32 - FM THR TIL 457 M
---	---------	--

WBKL AD 2.20 LOCAL AERODROME REGULATIONS

2.20.4 Pilots are advised to exercise caution when landing and take-off on affected areas of the runway.

2 VALIDITY

2.1 This AIRAC AIP Supplement will remain in force until 31st August 2024. Any updates, changes and cancellation of this AIRAC AIP supplement will be notified through NOTAM.

- END -