

---

**MALAYSIA**

PHONE: 6-03-8778 4106  
Email: ais@caam.gov.my  
URL: aip.caam.gov.my

CIVIL AVIATION AUTHORITY OF MALAYSIA  
AERONAUTICAL INFORMATION SERVICES  
AIR TRAFFIC CONTROL TOWER (TOWER WEST)  
JALAN KLIA 2/4,  
64000 KLIA,  
SELANGOR DARUL EHSAN  
MALAYSIA.

**AIRAC AIP SUP  
22/25**  
**Effective Date: 15 MAY 2025  
to UFN**  
Publication Date: 03 APR 2025

---

**KUALA LUMPUR INTERNATIONAL AIRPORT (WMKK)  
INTERMEDIATE HOLDING POSITION (IHP) LIGHTS TAXIWAY Z FROM INT Z4 UNTIL INT Z8**

**1 INTRODUCTION**

- 1.1 This AIRAC AIP Supplement is to inform all concerned about the unserviceability of the IHP lights TWY Z from INT Z4 until INT Z8.
- 1.2 Pilot to exercise caution during taxi.

**2 VALIDITY**

- 2.1 This AIRAC AIP Supplement will remain in force until further notice. Any updates, changes, and cancellations to this AIRAC AIP Supplement will be notified through NOTAM.

- END -